

Informations techniques/Technical Matters

Industries Bouchard, Inc.

La Pocatière, P.Q. Canada code 418 tel.: 856-1232 télex: 011-3486

December 28, 1970.

SUBJECT: NEW ANTI-SPILL VALVE FOR 1971 GAS TANK CAP.

To prevent any possible gas spillage by the gas tank cap

(all 1971 Moto Ski snowmobiles) a new valve kit (kit no: 1L.1007) is

now available from your distributor. This new anti-spill valve will

replace the actual one on all 1971 snowmobiles.

INSTALLATION PROCEDURE

NOTE: The kit is formed of the following:

a) 1 only Anti Spill valve part no: 10.01.022

b) 1 only Felt Washer part no: 70.01.016

1. Remove the existing valve from the gas tank cap.

- Immerse the gas tank cap in hot water (minimum 160 F) for period of 3 to 4 minutes.
- Blow into the new valve to make sure that air can flow freely through it. If a resistance is felt unblock the (2) orifices (one at each end) with a small wire.
- 4. Position the felt washer into the warmed up gas tank cap.
- Press down (over the felt washer) the new valve into the gas tank cap.

REMARK: No labour time is allowed for this modification.

PRINTED IN CANADA

IMPRIMERIE FORTIN LTÉE LA POCATIÈRE

Roger Lamontagn

Technical Information Manager.